

INSTALLATION MANUAL

$K\Lambda RIZM\Lambda$ [luce]


















Do not operate with power supply connected.

10W MAX | AC220-240V | 50/60Hz | IP20 Die cast | Adjustable











To mount the track adaptor into the track system, first check that the selector knob (A) is at OFF position and the adaptor lock **B** is disengaged.




When installing the adaptor into the track, ensure that it is orientated correctly.




Rotate adaptor lock B clockwise 90° to connect the adaptor to the neutral circuit.






Rotate selector knob (A) to the position of desired circuit.






Circuit 1: Rotate the knob (A) 45° clockwise from the starting point OFF, to connect circuit 1.




Circuit 2: Rotate the knob (A) 90° anti-clockwise from the starting point OFF, to connect circuit 2.






Circuit 1: Rotate the knob (A) 135° clockwise from the starting point OFF, to connect circuit 3.



Circuit 3: Rotate the knob (A) 180° clockwise from the starting point OFF, to connect circuit 4.



Warnings:

- 1. Make sure that the product is installed properly before connecting to electricity.
- 2. Do not cover the fitting.
- 3. Maintenance and installation should only be carried out by a professional electrician.